

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

LETTER

"DOA SO-1 Approved"

June 9, 1977 S/M

813

Subject:

Vertically Adjustable Seat Refinement

Models Affected:

Serial Numbers Affected:

SERVICE

PA-28-140 Cherokee Cruiser	28-7425061 to 28-7725170 Inclusive,
PA-28-151 Cherokee Warrior	28-7415001 to 28-7615435 Inclusive,
PA-28-161 Cherokee Warrior II	28-7716001 to 28-7716073 Inclusive,
PA-28-180 Cherokee Archer	28-7405035 to 28-7505261 Inclusive,
PA-28-181 Cherokee Archer II	28-7690001 to 28-7790358 Inclusive,
PA-28R-200 Cherokee Arrow II	28R-7435035 to 28R-7635312 Inclusive,
PA-28R-201 Cherokee Arrow III	28R-7737002 to 28R-7737018 Inclusive,
PA-28R-201T Cherokee Turbo Arrow III	28R-7703001 to 28R-7703040 Inclusive,
PA-28-235 Cherokee Pathfinder	28R-7410027 to 28-7710009 Inclusive,
PA-32-260 Cherokee Six	32-7400010 to 32-7700012 Inclusive,
PA-32-300 Cherokee Six	32-7440028 to 32-7740045 Inclusive,
PA-32R-300 Cherokee Lance	32R-7680001 to 32R-7680207 Inclusive,
PA-34-200 Seneca	34-7450033 to 34-7450220 Inclusive,
PA-34-200T Seneca II	34-7570001 to 34-7770159 Inclusive

Compliance Time: At owner/operator's discretion.

<u>Purpose:</u> This Service Release announces the availability of an improved Pilot and Co-Pilot's seat vertical adjustment actuator control assembly. This new adjustment control allows easy and positive up and down adjustment of the seats and is retrofitable to all aircraft listed above.

Instructions: Contained in the appropriate kits specified in Material Required, below.

Material Required: (One kit required per seat):

- <u>PA-28 and PA-28R series specified above</u>; Kit No. 761 103V, Vertically Adjustable Seat Control Assy. Installation, left <u>and/or</u> right seat @ special reduced list price \$ 8.00J;
- <u>PA-32</u>, <u>PA-32R</u>, <u>PA-34</u> and <u>PA-34T</u> series specified above; Kit No. 761 104V, Vertically Adjustable Seat Control Assy. Installation, <u>left seat only</u> @ special reduced list price \$ 8.00J;
- 3. <u>PA-32</u>, PA-32R, PA-34 and PA-34T series specified above; Kit No. 761 105V, Vertically Adjustable Seat Control Assy. Installation, <u>right seat only</u> @ special reduced list price \$ 8.00J.

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This Service Release is effective upon receipt.

Summary: This product refinement is being offered at the above referenced special reduced price to encourage owner/operators to take advantage of this offer. Please contact your Piper Field Service Facility to obtain the appropriate refinement modification kit for your aircraft.